

ECN no. : Darfon-ECN-22006

<b>TO :</b> All Customers	<b>FM :</b> 達方電子.
<b>ATTN :</b>	
<b>FAX :</b>	<b>DATE :</b> 2022/12/15
<b>SUBJ :</b> 磁珠 BP3216 系列料號更新 <b>Bead Product's (BP3216 Series)Part Number Updated</b>	

**Description of Change**

**BP3216 系列，料號更新如下： BP3216 Series ， Part Number Updated as below：**

Current	Updated	Current	Updated
BP3216190TTSB	BP3216190TPSB	BP3216151TTSB	BP3216151TPSB
BP3216260TTSB	BP3216260TPSB	BP3216181TTSB	BP3216181TPSB
BP3216300TTSB	BP3216300TPSB	BP3216201TTSB	BP3216201TPSB
BP3216310TTSB	BP3216310TPSB	BP3216221TTSB	BP3216221TPSB
BP3216330TTSB	BP3216330TPSB	BP3216301TTSB	BP3216301TPSB
BP3216520TTSB	BP3216520TPSB	BP3216501TTSB	BP3216501TPSB
BP3216600TTSB	BP3216600TPSB	BP3216601TTSB	BP3216601TPSB
BP3216800TTSB	BP3216800TPSB	BP3216102TTSB	BP3216102TPSB
BP3216121TTSB	BP3216121TPSB		

**Reason for Change**

編碼錯誤，包裝碼誤植為T，經內部發現，重新編碼為 P

**Coding error, the packaging code was wrongly planted as T, after internal discovery, it was recoded as P**

**Description of Specifications**

**Disposition**

**Prepared by :**

Josh Wang

**Approved by :**

Alex Huang

**Customer Acceptance (pls sign and return to Darfon)**

**Customer by :** \_\_\_\_\_

註：一個月內客戶端未回覆視同同意變更內容